

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 5853

CSAH NO. 52

OVER THE

THE SOUTH BRANCH OF THE BUFFALO RIVER

DISTRICT 4 - CLAY COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION

BY

COLLINS ENGINEERS, INC.

JOB NO. 3512 (CEI 50)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 5853, Piers 1 and 2 and the North and South Abutments, were in good condition below water with no defects of structural significance observed. A light accumulation of timber debris was observed at Pier 2. The channel bottom appeared to be in stable condition with no evidence of significant scour or appreciable changes since the previous inspection.

INSPECTION FINDINGS:


- (A) The concrete piers and abutments were in good condition. Both abutments displayed minor vertical and diagonal cracks at random locations, ranging in width from hairline to 1/8 inch.
- (B) A light accumulation of branchy timber debris was observed at the upstream side of the downstream column at Pier 2.

RECOMMENDATIONS:

- (A) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.

Daniel G. Stromberg

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over two horizontal lines.

Date 6/30/2004 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.

A large, stylized handwritten signature in black ink, appearing to read 'Dan G. Stromberg', is written over two horizontal lines.

Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 5853

Feature Crossed: The South Branch of the Buffalo River

Feature Carried: CSAH No. 52

Location: District 4 - Clay County

Bridge Description: The superstructure consists of three spans of multiple steel beams supporting a reinforced concrete deck. The superstructure is supported by two reinforced concrete piers and two reinforced concrete abutments. The piers are numbered 1 and 2 starting from the south end of the bridge. No design plans were available.

2. INSPECTION DATA

Professional Engineer/Team Leader: Shirley M. Walker, P.E.

Dive Team: Michelle D. Koerbel, Clayton G. Brookins

Date: October 29, 2002

Weather Conditions: Snow/Rain, " 35EF

Underwater Visibility: " 2 feet

Waterway Velocity: Negligible/None

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 and 2, North and South Abutments.

General Shape: The piers consist of two circular concrete shafts supporting a common hammerhead pier cap. The abutments consist of concrete vertical walls with adjacent skewed wingwalls. It is not known if the piers and abutments are supported on piles, due to the unavailability of design plans.

Maximum Water Depth at Substructure Inspected: Approximately 5 Feet.

4. WATERLINE DATUM

Water Level Reference: The top of the cap on the west end of Pier 2.

Water Surface: The waterline was approximately 10.5 feet below reference.
Assumed Waterline Elevation = 89.5.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 7



Item 61: Channel and Channel Protection: Code 7

Item 92B: Underwater Inspection: Code B/10/02


Item 113: Scour Critical Bridges: Code 1/95

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.

_____Yes X No



SOUNDING PLAN



TYPICAL END VIEW OF PIERS

GENERAL NOTES:

1. The North and South Abutments, and Piers 1 and 2 were inspected underwater.
2. At the time of inspection on October 29, 2002, the waterline was located approximately 10.5 feet below the top of the pier cap at the upstream end of Pier 2. Since insufficient bridge elevation information was available a reference elevation of 100.0 was assumed. Based on the assumed the reference the waterline elevation was 89.5.
3. Soundings indicate the water depth at the time of inspection and are measured in feet.
4. Soundings were taken parallel to the bridge at 1/4 point intervals between the substructure units.

INSPECTION NOTES:

- 1 The channel bottom consisted of silt and cobbles, up to 6 inches in diameter, with a maximum probe rod penetration of 1 foot.
- 2 The channel bottom consisted of silt and riprap, up to 12 inches in diameter, with a maximum probe rod penetration of 2 inches.
- 3 The channel bottom consisted of soft silt with a maximum probe rod penetration of 2 feet.
- 4 The concrete columns of the piers were in good and sound condition with no structurally significant defects observed.
- 5 The concrete of the abutments exhibited minor vertical and diagonal cracks at random locations, ranging in width from hairline to 1/8 inch.
- 6 A light accumulation of branchy timber debris was observed at the upstream side of the downstream column at Pier 2.

Legend

-2.0 Sounding Depth from Waterline (10/29/02)
-5.2 Sounding Depth from Waterline (9/10/97)

 Timber Debris

**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**


STRUCTURE NO. 5853
OVER THE SOUTH BRANCH OF THE BUFFALO RIVER
DISTRICT 4, CLAY COUNTY

INSPECTION AND SOUNDING PLAN


Drawn By: PRH
Checked By: MDK
Code: 35I20050

COLLINS ENGINEERS, INC.
 300 W. WASHINGTON, STE. 600
CHICAGO, ILLINOIS 60606
(312) 704-9300

Date: OCT. 2002
Scale: NTS
Figure No.: I



UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:

Refer to Figure 1 for General Notes.

**MINNESOTA
DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION**

STRUCTURE NO. 5853
OVER THE SOUTH BRANCH OF THE BUFFALO RIVER
DISTRICT 4, CLAY COUNTY

**UPSTREAM AND DOWNSTREAM
FASCIA PROFILES**

Drawn By: PRH

Checked By: MDK

Code: 35120050

COLLINS ENGINEERS, INC.
300 W. WASHINGTON, STE. 600
CHICAGO, ILLINOIS 60606
(312) 704-9300

Date: OCT. 2002

Scale: 1"=10'

Figure No.: 2



Photograph 1. View of Pier 1, Looking Northwest.



Photograph 2. View of Pier 2, Looking Southwest.



Photograph 3. View of South Abutment, Looking Southwest.



Photograph 4. View of North Abutment, Looking West.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: October 29, 2002
ON-SITE TEAM LEADER: Shirley M. Walker, P.E.
BRIDGE NO: 5853 WEATHER: Snow/Rain, " 35EF
WATERWAY CROSSED: The South Branch of the Buffalo River
DIVING OPERATION: X SCUBA SURFACE SUPPLIED AIR
OTHER
PERSONNEL: Michelle D. Koerbel, Clayton G. Brookins
EQUIPMENT: Scuba, U/W Light, Scraper, Sounding Pole, Lead Line, Probe Rod, Camera
TIME IN WATER: 10:10 a.m.
TIME OUT OF WATER: 10:30 a.m.
WATERWAY DATA: VELOCITY Negligible/None
VISIBILITY " 2 feet
DEPTH 5 feet maximum at Pier 2
ELEMENTS INSPECTED: Piers 1 and 2, North and South Abutments
REMARKS: Overall, the piers and abutments were in good condition with no defects of structural significance observed; however, minor hairline to 1/8 inch wide cracking was observed at the North and South Abutments. A light accumulation of branchy timber debris was observed at the upstream side of the downstream column at Pier 2. The channel bottom appeared to be stable with no significant scour.

FURTHER ACTION NEEDED: _____ YES ____X____ NO

Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 5853
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Shirley M. Walker, P.E.
WATERWAY CROSSED The South Branch of the Buffalo River

INSPECTION DATE October 29, 2002
NOTE: USE ALL APPLICABLE CONDITION
DEFINITIONS AS DEFINED IN THE MINNESOTA
RECORDING AND CODING GUIDE INCLUDING
GENERAL, SUBSTRUCTURE, CHANNEL AND
PROTECTION, AND CULVERTS AND WALL
DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	South Abutment	1.0'	N	7	N	9	N	7	8	8	8	N	8	7	N	N	N	N	N
	Pier 1	4.0'	N	7	N	9	N	7	8	N	N	N	8	7	N	N	N	N	N
	Pier 2	5.0'	N	7	N	9	N	7	8	N	N	7	7	7	N	N	N	N	N
	North Abutment	3.0'	N	7	N	9	N	7	8	8	8	N	8	7	N	N	N	N	N

*UNDERWATER PORTION ONLY

REMARKS: Overall, the piers and abutments were in good condition with no defects of structural significance observed; however, minor hairline to 1/8 inch wide cracking was observed at the North and South Abutments. A light accumulation of branchy timber debris was observed at the upstream side of the downstream column at Pier 2. The channel bottom appeared to be stable with no significant scour.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO.
USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.